

FLEXICRAFT[®] and No-Tox[®] Waterbased Inks TROUBLESHOOTING GUIDE

NS12
(09/14)

Dirty Printing:

- Check for worn or dirty anilox. Clean or replace if necessary.
- Wash plates
- Ink may be drying too fast. Adjust with slower drying blend.
- Check pH of ink. Optimum range 8.8-9.5. If below 8.8, slowly raise by adding small amount of aqueous ammonia.
- Viscosity may be too high. Reduce ink by adding the following and blend thoroughly:
 - a.) Water
 - b.) Water/propylene glycol blend
- Check heaters/air flow. Too much heat directed on plates may inhibit ink transfer to substrate.

Ink Drying Too Slow:

- Check airflow from dryers. Clean if appropriate and raise temperature if possible. Balance.
- Ink viscosity may be too low (too much water present). Add fresh ink.
- If ink can tolerate a viscosity reduction use either a 2:1 or 1:1 blend of water: isopropyl alcohol.

Never add alcohol alone!

Mix with water before adding.

Ink Drying Too Fast:

- Adjust dryers and airflow to minimize direct contact with printing plate or fountain.
- Add water, propylene glycol, or a blend of the two to retard drying.
- Check pH. Adjust to 8.8-9.5 if necessary.

Color Too Strong: (when checked at running speed)

- Reduce with required diluent (depending on drying conditions-see above) to no lower than 25-30 sec. #2 Zahn Cup.
- If still strong at 25-30 sec. and print quality o.k. do not use additional solvent. Use extender varnish to reduce color strength.

Color Too Weak: (when checked at running speed)

- Check anilox. If dirty, clean. If graphics will tolerate, change anilox to increase cell volume.
- Raise viscosity with fresh ink, being careful not to negatively alter drying rate.

Foaming:

- Check ink level in pump and fountain. Keep as full as possible. Pump slowly, not at high speed.
- Increase ink viscosity by addition of fresh ink.
- Use defoamer, a 50:50 blend with isopropyl alcohol or a 50:50 blend of water and isopropyl alcohol. Spray gently over foaming surface.

Adhesion: (especially to non-porous substrates)

- Allow ink to thoroughly dry. Printing onto non-porous materials may require higher temperatures than when printing porous substrates.
- Check pre-treatment level of stock if ink not adhering. Try fresh stock, or treat, if possible.
- Increase viscosity by adding fresh ink.

Pinholing: (non-porous substrates and some coated papers)

- Check treatment level of stock if appropriate. Try fresh stock, or treat, if level too low.
- Clean anilox or switch to greater cell volume (ink starvation)
- Check viscosity, may be too thin.

Clean-Up:

- Clean as soon after press is turned off as possible. Do not allow ink to set and harden on press parts or plates.
- Most clean-up can be achieved with a blend of water and alcohol. If ink has hardened, however, a commercial ammoniated cleaner and scrubbing may be required.



For more information, contact your Colorcon representative or call 1-800-724-0624
You can also visit our website at <http://www.colorcon.com/notox>

©BPSI Holdings LLC, 2014

The information contained in this document is proprietary to Colorcon Inc. and may not be used or disseminated inappropriately.

All trademarks, except where noted, are property of BPSI Holdings, LLC.

The information contained herein, to the best of Colorcon Inc.'s knowledge, is true and accurate. Any recommendations or suggestions of Colorcon Inc. with regard to the products provided by Colorcon Inc. are made without warranty, either implied or expressed, because of the variations in methods, conditions and equipment which may be used in commercially processing the products, and no such warranties are made for the suitability of the products for any applications that you may have disclosed. Colorcon Inc. shall not be liable for loss of profit or for incidental, special or consequential loss or damages. The information contained in this document is not intended as legal advice, and should not be relied upon for that purpose. Any regulatory information provided is intended solely as initial general guidance. Each customer is responsible for determining the regulatory acceptability of the use of the product in their specific application.